

construction engineering research laboratory



CHLORIDE SENSITIVITY OF THE CORROSION RATE OF ZINC-COATED REINFORCING BARS



Approved for public release; distribution unlimited.

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED

DO NOT RETURN IT TO THE ORIGINATOR

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered) READ INSTRUCTIONS REPORT DOCUMENTATION PAGE BEFORE COMPLETING FORM REPORT NUMBER 2. GOVT ACCESSION NO. 3. RECIPIENT'S CATALOG NUMBER INTERIM REPORT M-191 TITLE (and Substitut CHLORIDE SENSITIVITY OF THE CORROSION RATE OF ZINC-COATED REINFORCING BARS. INTERIM/ C./Hahin. S./Cato W. Mattheessen PERFORMING ORGANIZATION NAME AND ADDRESS PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS CONSTRUCTION ENGINEERING RESEARCH LABORATORY P.O. Box 4005 4A762719AT41-T7-002 Champaign, Illinois 61820 11. CONTROLLING OFFICE NAME AND ADDRESS 14. MONITORING AGENCY NAME & ADDRESS(If different from Controlling Office) UNCLASSIFIED 15a. DECLASSIFICATION/DOWNGRADING 16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. EKL-IK-M-19 -762717-A7 18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, VA 22151 19. KEY WORDS (Continue on reverse side if necessary and identify by block number) reinforcing bars 4-A-7627117-H71-41-7 zinc coating chloride sensitivi 20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This laboratory study was undertaken to determine whether zinc

This laboratory study was undertaken to determine whether zinc coatings can be relied on for long-term protection of reinforcing bars subject to environments of variable salt concentrations.

Hot-dip galvanized reinforcing bars were coupled to bare carbon steel rebars in various concentrations of $CaCl_2$ in saturated $Ca(OH)_2$ distilled water solutions. Galvanic current output was monitored as a

DD FORM 1473

EDITION OF 1 NOV 65 IS OBSOLETE
405271

UNCLASSIFIED


SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

FOREWORD

This research was conducted for the Directorate of Military Construction, Office of Chief of Engineers (OCE), under QCR 1.03.007, Project 4A762719AT41, "Design, Construction, and Operations and Maintenance Technology for Military Facilities," Task T7, "Materials Research and Development for Military Construction," Work Unit 002, "Corrosion Effects on Construction Materials." The work was performed by the Metallurgy Branch, Materials and Science Division of the U.S. Army Construction Engineering Research Laboratory (CERL).

OCE Technical Monitor for the work is Mr. C. Damico, DAEN-MCC-C.

Dr. A. Kumar is Chief of the Metallurgy Branch and Dr. G. Williamson is Chief of the Materials and Science Division. COL J. E. Hays is Commander and Director of CERL and Dr. L. R. Shaffer is Deputy Director.



CONTENTS

	DD FORM 1473 FOREWORD LIST OF FIGURES AND TABLES	1 3 5
1	INTRODUCTION	7
2	BACKGROUND	8
3	EXPERIMENTAL PROCEDURES	18
4	RESULTS AND DISCUSSION	22
5	CONCLUSIONS AND RECOMMENDATIONS	27
	REFERENCES 2 DISTRIBUTION 2	29

FIGURES

Number		Page	
1	Potentials of Steel Wire in Solution After Surface Abrasion		
2	Precast Reinforced Concrete Panels Exposed to Rural Atmosphere With 1/4 in. [0.6 cm] Cover in the Spall Zones		
3 a	Underlayment of Trestle Showing Spalling of Concrete and Corrosion of Steel Supports		
3b	Deterioration of Reinforced Concrete Beam of Same Rail Trestle		
4	Failure Mechanisms in Concrete Exposed to Fresh and Saline Waters	17	
5	Test Apparatus for Measuring Galvanic Output of Zinc-Coated Bars	20	
6	Ammeter Junction Box and Shorting-Switch	21	
7	Galvanized Rebar-Steel Rebar Couple in O Percent CaCl ₂	23	
8	Galvanized Rebar-Steel Rebar Couple in 0.01 Percent CaCl ₂	23	
9	Galvanized Rebar-Steel Rebar Couple in O.1 Percent CaCl ₂	24	
10	Galvanized Rebar-Steel Rebar Couple in 1.0 Percent CaCl ₂	24	
11	Galvanized Rebar-Steel Rebar Couple in 2.0 Percent CaCl ₂	25	
12	Galvanized Rebar-Steel Rebar Couple in 4.0 Percent CaCl ₂	25	
13	Galvanic Current Output of Zinc-to-Steel Couples as a Function of CaCl ₂ Concentration in Saturated Ca(OH) ₂ -Distilled Water Solution	26	
	TABLE		
1	Average Thickness of Zinc Coating	19	

CHLORIDE SENSITIVITY OF THE CORROSION RATE OF ZINC-COATED REINFORCING BARS

1 INTRODUCTION

Problem Statement

Concrete, when placed in contact with metals, may be corrosive, neutral, or protective. The response of metal to concrete depends on the alloy composition, the constituents of the concrete, and the environment or service in which the concrete structure is placed. Many new procedures have been suggested for preventing the corrosion of steel in concrete; the suitability of these procedures for Corps of Engineers applications must be investigated.

Objective and Scope

This report documents part of a study to evaluate newly developed procedures for preventing corrosion of steel in concrete with respect to their suitability for inclusion in Corps of Engineers guide specifications.

The effectiveness of the procedures will be evaluated by several criteria. First, how much longevity can be expected and can any means be developed to predict this life? Second, does the procedure cause stress or deterioration of the concrete? Third, is the procedure economical and can it be expected to remain so for several years?

This interim report documents preliminary results of work on zinc-coated reinforcing bars exposed to alkaline and alkaline-chloride media. It considers only the first study criterion--longevity. Future study will complete the evaluation of longevity and address stress-deterioration and economic considerations.

Approach

The study phase reported here was accomplished as follows:

- 1. Literature was reviewed to place this experiment in the context of prior studies (Chapter 2).
- 2. Laboratory tests were performed on zinc-coated steel bars coupled to bare bars of equal length to determine the effect of chloride concentration on the corrosion rate of zinc (Chapter 3). The bars were submerged for 50 days in calcium chloride solutions of different concentrations, and corrosion rates were plotted as a function of time for each concentration.

2 BACKGROUND

This chapter reviews prior studies, describes the effects of concrete environments on steels, and discusses current thinking on the relationship between concrete cover and composition and its life span.

Response of Steel to Concrete

Portland cement in its dry state is composed of calcium oxide (CaO), silicon dioxide (SiO_2) , and various other oxides. When water is added to concrete, the cement oxides form hydroxides and other cement mineral complexes which bind the aggregate. Water combines with CaO to form calcium hydroxide $(Ca(OH)_2)$, the principal passivating agent in the concrete. The other constituents of concrete--sand, stone, and unground cement clinker--are essentially inert. Uncombined water, which does not participate in the cement hydration and hardening reactions, acts as the solvent for carbonates, sulfates, and hydroxides in the concrete. This uncombined water solution may be a good or poor conductor, depending on which ions are dissolved in it and their concentrations.

The surface of a steel reinforcing bar reacts immediately with the alkaline concrete slurry to form ferrous hydroxide (Fe(0H)₂), which in turn reacts with dissolved oxygen to form γ -Fe₂0₃ or Fe₃0₄. An imperfect oxide film halts corrosion of the steel, preventing further iron ions from going into solution. The oxide film remains intact as long as a uniform supply of hydroxyl ions and oxygen surrounds the entire surface of the bar.

The minimum pH required for passivation of steel in concrete has been reported to be 11.5, although potential-pH (Pourbaix) diagrams have shown the minimum pH to be dependent on the potential of the steel. Since the pH of saturated $Ca(0H)_2$ is 12.5, the concrete in the vicinity of the bar remains basic as long as sufficient concentrations of hydroxyl ion are present. The pH is a direct measure of this hydroxyl ion concentration.

The passivation of a <u>bare</u> steel surface occurs quickly, as Hausmann⁴ demonstrated in both saturated $Ca(OH)_2$ and a Portland cement slurry (see Figure 1). As seen in Figure 1, the steel corrosion potentials of all


¹D. Lewis and W. Copenhagen, "Corrosion of Reinforcing Steel in Concrete in Marine Atmospheres." Commaging Vol. 15 (1959), p. 382

in Marine Atmospheres," *Corrosion*, Vol 15 (1959), p 382.

R. Shalon and M. Raphel, "Influence of Seawater on Corrosion Reinforcement," *Proceedings of the ACI*, Vol 55 (1958-9), p 1251.

³M. Pourbaix, "Application of Electrochemical Thermodynamics," *Lectures on Electrochemical Corrosion* (Plenum Publishing Corporation, 1973), p 19.

^{*}D. Hausman, "Steel Corrosion in Concrete," *Materials Protection*, Vol 6, No. 11 (1967), p 19.



Potentials of steel wire in solution after surface abrasion. Reprinted with permission of the National Association of Corrosion Engineers from D. Hausman, "Steel Corrosion in Concrete," Materials Protection, Vol 6, No. 11 (1967), p 19. Figure 1.

the higher pH solutions became more positive (nobler) with time, whereas the neutral water solution (pH = 7) started to become passive but then rapidly broke down. Depassivation can also occur rapidly on a bare steel surface, which implies that the stability of protective films on steel is environment-sensitive.

Cracking of Concrete in Saline Solutions

Concrete is a heterogeneous solid composed of many particles which vary in size from microscopic to macroscopic dimensions. Some of the particles are engaged in bonding, some fill voids, and others are inert. Concrete has high concentrations of voids, many of which are interconnected. These voids may contain water filled with ions in solution, or they may be dry. Since concrete is not completely solid, there are many diffusion paths and capillary passageways where moisture can filter in and out.

Other structural inhomogeneities may develop in concrete, such as cracks resulting from shrinkage or loading, or the uneven distribution of aggregate particles because of poor mixing or pouring practices. These inhomogeneities cause permeability and capillarity to vary throughout the concrete. Variances in the properties of concrete can lead to formation of sites with high oxygen concentrations or low pH.

In fresh water with high resistivity (> 10,000 ohm-cm), ionic concentrations are insufficient to cause major changes in oxygen concentration. Unless the concrete cracks in spots and residual Ca(0H)2 is washed away, the pH will remain >11.5. Although the initial driving potentials of differential aeration cells in low conductivity solutions are low (10 to 20 mV), they increase to substantial values after corrosion begins. The depth of cover is significant in damping out these variations in oxygen, dissolved solids, and pH. The wisdom of American Concrete Institute requirements for minimum concrete cover over reinforcing bars is evident in Figure 2, where a light concrete (< 1/2 in. [1.3 cm]) skin on a precast concrete panel shows excessive spalling and discoloration. This structure is not exposed to industrial pollution and sustains only moderate rainfall. Figure 3 is the underside of a rail trestle showing advanced deterioration where water seepage from above has passed through cinders and caused spalling.

H. Uhlig, "The Oxygen Electrode and Differential Aeration Cell," Corrosion and Corrosion Control (John Wiley and Sons, Inc., 1971), pp 26-27.

⁶American Concrete Institute Standard 318-71, Building Code Requirements for Reinforced Concrete (American Concrete Institute, 1971), p 21.



Precast reinforced concrete panels exposed to rural atmosphere with 1/4 in. [0.6 cm] cover in the spall zones. Figure 2.



Figure 3a. Underlayment of trestle showing spalling of concrete and corrosion of steel supports.



Deterioration of reinforced concrete beam of same rail trestle. Cover is about 1 to 1 1/2 in. $[2.5-3.8~\rm cm]$. Note severe cracking of beam at mid-section on right. Figure 3b.

Carbon dioxide can react with the Ca(OH)₂ to yield CaCO₃, which also lowers pH. If cracking is induced by mechanical loading or thermal stresses, a seepage of slightly acidic water can also deplete the supply of hydroxyl ions.

However, if the concrete is in a more hostile environment, such as in a salt water estuary or acidic mine waters, the depletion of Ca(OH)2 surrounding the steel can occur more rapidly. Chlorides are especially problematic because of their abundance in both fresh and salt waters. The wide use of deicing salts on highway pavements and bridges also represents a major source of concrete deterioration induced by rebar corrosion.

Adding ions like Cl⁻ to concrete increases the conductivity of the concrete and the ion concentrations may vary sharply since concrete is inhomogeneous. When the concrete is first exposed to a saline environment, the low Cl⁻ concentration in the concrete will gradually increase to that of the surrounding environment through uptake of the bulk fluid by capillarity and diffusion. However, several investigators^{8,9,10} found that after prolonged exposure, the concentrations were much greater than in the bulk solution. In the San Mateo bridge, ¹¹ exposed for more than 30 years, concentrations were almost equal to saturated sodium chloride (NaCl) (26 percent) whereas the bay concentration is only about 4 percent salt.

Stratfull¹² has proposed that chloride accumulation proceeds by gradual bulk fluid absorbtion by capillarity, and that chloride concentration eventually occurs as the water of solution evaporates during the drying cycle. Stratfull also correlated the evaporable water content to water-cement ratio by an empirical equation:

$$E = k \frac{W^{1-2}}{C^{0-72}} + C_0$$

⁸R. Stratfull, "Corrosion of Reinforced Concrete Bridge," *Corrosion*, Vol 13 (1957), p 173.

¹⁰H. Finley, "Corrosion of Reinforcing Steel in Concrete Marine Atmospheres," Corrosion, Vol 17 (1961), p 104.

¹¹Finley, p 104.¹²R. Stratfull, "How Chlorides Affect Concrete Used with

¹²R. Stratfull, "How Chlorides Affect Concrete Used with Reinforcing Steel," *Materials Protection*, Vol 7 (1968), p 29.

A. Tripler and W. Boyd, "Corrosion of Reinforcing Bars in Concrete," Proceedings of the 24th National Association of Corrosion Engineers Conference (Houston, 1968), p 322.

⁹J. Beaton, D. Spellman, and R. Stratfull, "Corrosion of Steel in Continuously Submerged Reinforced Concrete Piling," *Highway Research Board Record*, Vol 204 (1967), p 11.

where E = evaporable water content

W = percent water added to concrete mix

C = sacks of cement per cubic yard of concrete

 $k,c_0 = empirical constants.$

Stratfull found that concretes which were allowed to air-dry rather than fog- or steam-cure were highly absorbtive. High water-to-cement ratio concretes lost water quickly, which rendered them more susceptible to chloride intake.

Other investigators, like Atimtay and Ferguson, 13 have recommended a minimum water-to-cement ratio of 5.5 gal/sack. The more moisture the concrete contains as a result of curing, coupled with increased cement content, the better resistance to cracking.

Since even high quality concretes sustain cracks and take in chlorides, appreciable changes can occur in the vicinity of the rebar as varying concentrations of chloride build up. As chloride concentration increases, the solubility of oxygen decreases. This sets up cells where oxygen is excluded, and solvation of iron takes place more readily. The cause of this increased solvation tendency of iron in the presence of Cl⁻ has been the subject of much speculation. The most prominent theories are (1) competitive absorption of Cl⁻, (2) penetration of Cl⁻ through the passive layer, (3) formation of iron complexes, and (4) electrostatic attraction of Cl⁻ to iron.

However, the accumulation of Cl in a confined region such as a crevice or pit causes acidification through hydrolysis of an acid salt: 14

$$FeC1_2 + 2H_2O \rightarrow Fe(OH)_2 + 2HC1$$

The oxygen depletion of this confined area prevents the formation of ferric hydroxide or hydrated oxides, which can stifle further reaction of iron. These corrosion products precipitate some distance from the oxygen-depleted area in a region where more oxygen is available. The electrons generated by ionization of iron are consumed by the reaction:

$$0_2 + H_2 O + 4e^- \rightarrow 40H^-$$

which occurs at an adjacent non-acidic cathodic site. This series of events is the onset of chloride attack.

14M. Fontana and N. Greene, Corrosion Engineering (McGraw-Hill, 1967), p 43.

Concrete," Journal of American Concrete Institute, Vol 70-9 (1973), p 606.

There is considerable disagreement as to what threshold level of Cl is responsible for premature failure of concrete. A Cl threshold of 700 ppm has been reported, 15 although Newman 16 and Blenkinsop 17 noted that up to 2 percent CaCl2 in concrete admixtures had no detrimental effect. Approximately half the CaCl2 admixture becomes free Cl, according to Wohlhuter and Morris. 18

As more and more of the corrosion products of iron are produced, the greater the space they occupy. Eventually, as the corrosion products occupy more space than the interface will permit, the concrete must expand. Since concrete is weak in tension, cracking and spalling will then occur. Cracking, in turn, permits more influx of the corrosive environment to leach out $\text{Ca}(\text{OH})_2$ and more easily release corrosion products. The thickness of the concrete cover also is related to this cracking, since thick covers can accommodate greater corrosion product pressures than thin covers. These failure mechanisms are diagrammed in Figure 4.

The Problem of Protective Coatings

Both metallic and nonmetallic coatings have been investigated as corrosion-preventive coverings for rebars. Of the metallic coatings, zinc has been most widely used because of its sacrificial nature and fairly low cost. Although zinc corrodes rapidly in highly acid (<pH3) or highly alkaline (>pH13) solutions, 20 it has a very low corrosion rate in the pH ranges of ordinary Portland cement concrete (11.5 to 13). Unless the cement contains potassium or sodium oxides, the pH should be no greater than 12.5--the pH of saturated Ca(OH)2. Zinc coatings on bars do not impair bonding properties, but are reported 21 to be better or at least equal to the bond strength of bare steel to concrete.

¹⁶A. Newman, "Effects of Addition of CaCl₂ to Portland Cement Concrete," Concrete and Construction Engineering, Vol 38 (1943), p 159.

¹⁸C. Wohlhuter and R. Morris, "Aspects of Steel Corrosion in Concrete," Die Siviele Ingenieur in Suid-Afrika, Vol 15-9 (1973), p 245.

19J. Clifton, A. Beeghly, and R. Mathey, Nonmetallic Coatings for Concrete Reinforcing Bars, Report PB 236-424 (Federal Highway Administration, February 1974).

²⁰B. Roetheli, G. Cox, and W. Littreal, "Effect of pH on the Corrosion Products and Corrosion Rate of Zn in Oxygenated Aqueous Solutions," Metals and Alloys, Vol 3 (1932), p 73.

²¹I. Cornet and B. Bresler, "Corrosion of Steel and Galvanized Steel in Concrete," *Materials Protection*, Vol 5, No. 4 (1966), p 69.

¹⁵D. Hausman, "Steel Corrosion in Concrete," *Materials Protection*, Vol 6, No. 11 (1967), p 19.

¹⁷J. Blenkinsop, "Effect on Normal 3/8 in. Reinforcement of Adding CaCl₂ to Dense and Porous Concretes," Magazine of Concrete Research, Vol 15-43 (1963), p 33.




Figure 4. Failure mechanisms in concrete exposed to fresh and saline waters.

Tripler and Boyd²² reported in their potentiodynamic studies of zinc in 3.5 percent NaCl and saturated Ca(OH)2, that the passivating reaction is the formation of Zn(OH)2. Film breakdown occurs with the formation of ZnCl₂. Chlorides therefore accelerate the corrosion rate by rupturing a Zn(OH)2 film which acts as a corrosion barrier. Hoxeng and Prutton²³ demonstrated that increasingly slight additions of Cl⁻ (10 to 50 ppm) to synthetic tap water solutions actively raised potentials of zinc by nearly 0.3V. Hubbard and Shanahan noted similar active shifts of zinc in aqueous solutions of increasing Cl content up to 100 ppm.²⁴ More active shifts meant increased corrosion rates with more Cl content in these studies, although they were not conducted in alkaline media. If reinforcing ber is to be protected by zinc for long periods of time, some measurement of the corrosion rate of zinc in varying concentrations of Cl is needed for prediction of rebar life.

Since prior work has not considered the deterioration of zinc in alkaline-chloride media, this study was intended to test zinc sensitivity in both saturated Ca(OH)2 and actual concrete. Moreover, direct measurement of the kinetics of zinc consumption was sought instead of more conventional potential studies.

3 EXPERIMENTAL PROCEDURES

Testing Apparatus

Steel reinforcing bars (#4 deformed bars) were commercially hot-dip galvanized with Prime Western grade zinc. The average thickness of the zinc coating was determined by (1) cross-sectioning random portions of the rebar, (2) metallurgically polishing each section and etching with nitric acid and methyl alcohol, and (3) measuring the coating with a Zeiss optical microscope with a calibrated filar eyepiece. The average thickness was 0.152 mm; thickness variations are reported in Table 1.

Each bar was drilled on each cut end to accept a solid #12 gauge copper wire. After 0.8 in. (2 cm) of TW wire insulation was stripped away, the copper wires were soldered to the reinforcing bars on each end. The soldered joint was sealed with General Electric RTV silicone compound.

²³R. Hoxeng and C. Prutton, "Electrochemical Behavior of Zinc and Steel

²²A. Tripler and W. Boyd, "Corrosion of Reinforcing Bars in Concrete," Proceedings of the 24th National Association of Corrosion Engineers Conference (Houston, 1968), p 322.

in Aqueous Media," *Corrosion*, Vol 5 (1949), p 330.
²⁴D. Hubbard and C. Shanahan, "Corrosion of Zinc and Steel in Dilute Aqueous Solutions, "British Corrosion Journal, Vol 8 (November 1973), p 270.

Table 1
Average Thickness of Zinc Coating

Sample Number	No. of Readings	Avg. Thickness, mm
1	9	0.17
2	7	0.16
3	7	0.17
4	7	0.15
5	8	0.15
6	7	0.11

A banana plug was soldered to the end of each copper lead wire to obtain current and resistance measurements. Each galvanized reinforcing bar had a companion uncoated deformed bar of equal length and nominal diameter. All bars were 16 in. (40.6 cm) long and were weighed to the nearest 0.01 q.

The testing apparatus (Figure 5) consisted of a 50-liter polyethylene tank which provided an immersion bath for the bars. Bars were suspended in the tank by a notched, paraffin wax-impregnated wooden rack which kept the bars equidistant from each other. Two-in. (5.1 cm) centers were maintained to prevent variances in voltage drop from specimen to specimen. The wooden frames were suspended by stainless steel rods.

Each tank held a different concentration of CaCl2 in a saturated solution of $Ca(OH)_2$ dissolved in distilled water. One control solution contained only saturated $Ca(OH)_2$. Each container held two couples (4 bars total) plus a galvanized uncoupled bar. All bars were fully immersed at all times.

Each coated bar was galvanically coupled to an uncoated bar via a junction box. When current flow was measured, a switching arrangement placed an ammeter directly in series with the bar without interrupting current flow (see Figure 6).

An uncoupled galvanized control bar was also placed in the suspension rack, with copper leads attached for potential and resistance measurements.

Test Procedures

The current output of every couple was read daily with a Keithley Model 164 Digital Multimeter, sensitive to \pm 0.1 nA and having 0.2





Figure 5. Test apparatus for measuring galvanic output of zinc-coated bars. Bars are uniformly 2 in. apart.



JI = INPUT JACK TO BAR (Zn coaled)

JZ = INPUT JACK TO BAR (Steel)

SWI = SHORTING SWITCH (normally on)

J3, J4 = POTENTIAL DIFFERENCE JACKS

J5, J6 = AMMETER JACKS

SW2 = SWITCH ENGAGED WHEN

READING AMPERAGE;

SWI MUST BE IN OFF

POSITION

Figure 6. Ammeter junction box and shorting-switch.

percent accuracy in the milliampere range. Changes in the resistance of each coated bar were also measured by this instrument weekly.

Temperature variations in the container were sensed by a capillary bulb of a Taylor Instrument thermograph. Average temperature was $68 \pm 3^{\circ}F$ (293 + $2^{\circ}K$).

After each reading, the ammeter was removed from the circuit via the junction box without halting current flow, and the bar remained coupled until the next reading period. Times were noted to determine ampere-seconds (coulombs) for weight loss calculations.

Corrosion rates were calculated by the following equation:

$$mpy = \frac{129 \text{ iM}}{zp}$$

where mpy = corrosion rate in mils/yr (0.0254 mm = 1 mil)

i = corrosion current, mA/cm²

z = number of electrons transferred

M = average gram-atomic weight

 $\rho = density.$

Two couples were placed in a saturated $Ca(OH)_2$ -distilled water solution along with one galvanized uncoupled bar. Similarly, bars were placed in solutions containing 0.01 percent, 0.1 percent, 1 percent, 2 percent, and 4 percent $CaCl_2$ in a saturated $Ca(OH)_2$.

The resistivity of each solution was measured by a Yellow Springs Instrument Model 31 conductivity bridge.

4 RESULTS AND DISCUSSION

The measured galvanic current flow between the zinc-coated bar and the bare steel bar is plotted in Figures 7 through 12. The concentrations of CaCl₂ in the saturated Ca(OH)₂ are also shown.

The bars in distilled water and $Ca(OH)_2$ (see Figure 7) show a current vs. time-of-exposure curve that rapidly decays in the first few days. After the rapid decay, a relatively stable plateau develops due to buildup of $Zn(OH)_2$. Corrosion products further accumulate, resulting in a slow decay to a fairly low corrosion rate.

The addition of 0.01 percent CaCl2 does not significantly change the current output of the couple, which relatively parallels the decay of the chloride-free solution. Figure 8 shows this parallel trend.




Figure 7. Galvanized rebar-steel rebar couple in 0 percent CaCl₂.




Figure 8. Galvanized rebar-steel rebar couple in 0.01 percent CaCl₂.




Figure 9. Galvanized rebar-steel couple in 0.1 percent CaCl₂.




Figure 10. Galvanized rebar-steel rebar couple in 1.0 percent CaCl₂.




Figure 11. Galvanized rebar-steel couple in 2.0 percent $CaCl_2$.




Figure 12. Galvanized rebar-steel rebar couple in 4.0 percent CaCl₂.

Figure 9 reveals the same trend again at 0.1 percent CaCl₂, with less fluctuation and difference in the output of each couple.

As the percent of $CaCl_2$ is increased to the 1.0 percent level, the plateau region seen in lower chloride solutions after the initial decay disappears. The current output is cyclic, with peaks of activity occurring every 8 to 10 days, then exponentially decaying. As shown in Figures 11 and 12, increases in $CaCl_2$ result in greater swings in current output difference between peak and valley. Each peak represents a breakdown in the $Zn(OH)_2$ passive film by $ZnCl_2$ and each valley represents the buildup of $Zn(OH)_2$.

Figure 13 shows current output as a function of CaCl₂ concentration. For the first 10 days the corrosion rate rises linearly with log time. After 10 days, the corrosion rate is no longer linear but begins to jump exponentially at 4 percent CaCl₂.

The method of measuring current output of galvanic couples with a l:l cathode-to-anode area ratio can be used to correlate corrosion rates of other anode-to-cathode area ratios. This can be accomplished since the area ratio is proportional to corrosion rate, as shown by Tripler




Figure 13. Galvanic current output of zinc-to-steel couples as a function of CaCl₂ concentration in saturated Ca(OH)₂-distilled water solution.

and Boyd.²⁵ The self-corrosion rate can be determined by solving the "catchment" equation:

$$p = P_0 (1 + A_c/A_a)$$

where p = new penetration after coupling

 P_0 = uncoupled penetration

 $A_r = area of cathode$

 A_a = area of anode.

However, the tests reported here are relative indications, and may not correspond exactly to zinc-dipped reinforcing bars of advanced age. Older bars would have similar anode-to-cathode area ratios, but current output might differ due to penetrations into the various phases of the zinc-iron binary solution.

Another problem is that the corrosion rates determined here may be applicable only to highly porous or ruptured-cover concretes, in which corrosion products are permitted to expand freely. The corrosion products of zinc may self-limit its own consumption in concrete, because the concrete may not permit further expansion. This factor was not evaluated in this study, since corrosion products formed freely and were not confined by concrete. Corrosion products tended to form in the valleys of the diamond-pattern of the reinforcing bar, and were somewhat knobby in shape and discontinuous in their distribution.

Resistance changes were found to be negligible.

5 CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 1. The galvanic corrosion rate of zinc in saturated $Ca(OH)_2$ was sensitive to the chloride concentration, and tended to rise perceptibly at \geq 1 percent $CaCl_2$, with an exponential rise at 4 percent $CaCl_2$.
- 2. A discontinuous distribution of corrosion products may result in localized stresses if zinc-coated bars are imbedded in concrete exposed to high-chloride environments. However, the nature of these corrosion product forces and their growth in concrete-cover confinements is not known since this investigation permitted free expansion.

²³A. Tripler and W. Boyd, "Corrosion of Reinforcing Bars in Concrete," Proceedings of the 24th National Association of Corrosion Engineers Conference (Houston, 1968), p 322.

3. The proportionality of anode-to-cathode area ratio to corrosion rate for ratios <1 was not evaluated in this study, although the Tripler and Boyd 26 work established a basis to use this galvanic couple to determine actual corrosion rates by extrapolation. This study indicates that zinc-coated bars coupled to bare bars of equal length would sustain the same sensitivity to chlorides.

Recommendations

- 1. The corrosion rate of zinc concentrations >1 percent CaCl2 in actual concrete should be evaluated to establish correlation with this laboratory simulation. This should be accomplished using actual bars with known cover-to-bar diameter and water-cement ratios. The proportionality of anode-to-cathode ratio to corrosion rate should also be analyzed for the possibility of using test couples throughout the concrete for predicting corrosion rates of fully coated bars.
- 2. The measurement of voltage in proportion to current should be evaluated over a longer period of time.
- 3. The nature of the stresses generated by the corrosion products of iron and zinc should be evaluated in-situ. Theoretical computations of expansion due to formation of iron oxide-hydroxides or chlorides cannot accurately predict stresses, since corrosion-product confinement is related to permeability and the strength of the concrete-metal interface.
- 4. Quicker and more accurate methods of determining chloride content profiles as a function of depth in concrete require further development for better prediction of corrosion rate.
- 5. Because the corrosion rate of zinc in concrete is chloridesensitive, a Corps-wide adoption of zinc-coated bars cannot be recommended at this time. When accurate means of measuring the in-situ corrosion rate are completed, incorporation of zinc-coated rebars into existing guide specifications can then be considered.
- 6. A cost-benefit ratio analysis of the merits of zinc-coated bars compared to bare bars must also be completed prior to Corps acceptance.

²⁶A. Tripler and W. Boyd, "Corrosion of Reinforcing Bars in Concrete," Proceedings of the 24th National Association of Corrosion Engineers Conference (Houston, 1968), p 322.

REFERENCES

- American Concrete Institute Standard 318-71, Building Code Requirements for Reinforced Concrete (American Concrete Institute, 1971), p 21.
- Atimtay, E. and P. Ferguson, "Early Chloride Corrosion of Reinforced Concrete," Journal of American Concrete Institute, Vol 70-9 (1973), p 606.
- Beaton, J., D. Spellman, and R. Stratfull, "Corrosion of Steel in Continuously Submerged Reinforced Concrete Piling," *Highway Research Board Record*, Vol 204 (1967), p 11.
- Blenkinsop, J., "Effect on Normal 3/8 in. Reinforcement of Adding CaCl₂ to Dense and Porous Concretes," *Magazine of Concrete Research*, Vol 15-43 (1963), p 33.
- Clifton, J., A. Beeghly, and R. Mathey, Nonmetallic Coatings for Concrete Reinforcing Bars, Report PB 236-424 (Federal Highway Administration, February 1974).
- Cornet, I. and B. Bresler, "Corrosic of Steel and Selvanized Steel in Concrete," Materials Protection, Vol 5, No. 4 (1966), p 69.
- Finley, H., "Corrosion of Reinforcing Steel in Concrete Marine Atmospheres," *Corrosion*, Vol 17 (1961), p 104.
- Fontana, M. and N. Greene, Corrosion Engineering (McGraw-Hill, 1967), p 43.
- Hausman, D., "Steel Corrosion in Concrete," Materials Protection, Vol 6,
 No. 11 (1967), p 19.
- Hoxeng, R. and C. Prutton, "Electrochemical Behavior of Zinc and Steel in Aqueous Media," *Corrosion*, Vol 5 (1949), p 330.
- Hubbard, D. and C. Shanahan, "Corrosion of Zinc and Steel in Dilute Aqueous Solutions," *British Corrosion Journal*, Vol 8 (November, 1973), p 270.
- Lewis, D. and W. Copenhagen, "Corrosion of Reinforcing Steel in Concrete in Marine Atmospheres," *Corrosion*, Vol 15 (1959), p 382.
- Newman, A., "Effects of Addition of CaCl₂ to Portland Cement Concrete," Concrete and Construction Engineering, Vol 38 (1943), p 159.
- Pourbaix, M., "Application of Electrochemical Thermodynamics," Lectures on Electrochemical Corrosion (Plenum Publishing Corporation, 1973), p 19.

REFERENCES (cont'd)

- Roetheli, B., G. Cox, and W. Littreal, "Effects of pH on the Corrosion Products and Corrosion Rate of Zn in Oxygenated Aqueous Solutions," Metals and Alloys, Vol 3 (1932), p 73.
- Shalon, R. and M. Raphel, "Influence of Seawater on Corrosion Reinforcement," *Proceedings of the ACI*, Vol 55 (1958-9), p 1251.
- Stratfull, R., "Corrosion of Reinforced Concrete Bridge," *Corrosion*, Vol 13 (1957), p 173.
- Stratfull, R., "How Chlorides Affect Concrete Used with Reinforcing Steel,"

 Materials Protection, Vol 7 (1968), p 29.
- Tripler, A. and W. Boyd, "Corrosion of Reinforcing Bars in Concrete,"

 Proceedings of the 24th National Association of Corrosion Engineers
 Conference (Houston, 1968), p 322.
- Uhlig, H., "The Oxygen Electrode and Differential Aeration Cell," Corrosion and Corrosion Control (John Wiley and Sons, Inc., 1971), pp 26-27.
- Wohlhuter, C. and R. Morris, "Aspects of Steel Corrosion in Concrete,"

 Die Siviele Ingenieur in Suid-Afrika, Vol 15-9 (1973), p 245.

CERL DISTRIBUTION

```
US Army Engineer District
New Orleans
ATTN: Library
ATTN: Chief, LMNED-DG
 Director of Facilities Engineering APO NY 09827
 DARCOM STIT-EUR
APO New York 09710
                                                                                                                                                                  (ittle Rock
ATTN: Chief, Engr Div
 West Point, NY 10996
ATTN: Dept of Mechanics
ATTN: Library
                                                                                                                                                                  Tulsa
ATTN: Library
                                                                                                                                                                  Albuquerque
ATTN: Library
Chief of Engineers
ATM: DAEN-ASI-L (?)
ATTM: DAEN-FEL
ATTM: DAEN-FESA
ATTM: DAEN-FESA
ATTM: DAEN-FEZ-A
ATTM: DAEN-MCZ-S
ATTM: DAEN-MCZ-S
ATTM: DAEN-MCZ-S
ATTM: DAEN-PMS (6)
for forwarding to
National Defense Headquarters
Director General of Construction
Ottawa, Ontario KIAOX2
Canada
                                                                                                                                                                   San Francisco
ATTN: Chief, Engr Div
                                                                                                                                                                   Sacramento
ATTN: Chief, SPKED-D
                                                                                                                                                                  Japan
ATTN: Library
                                                                                                                                                                    Portland
ATTN: Chief, DB-6
Seattle
ATTN: Chief, NPSCO
                                                                                                                                                                    Walla Walla
ATTN: Library
ATTN: Chief, Engr Div
                                                                                                                                                                    Alaska
        Canadian Forces Liaison Officer (4)
U.S. Army Mobility Equipment
Research and Development Command
Ft Belvoir, VA 22060
                                                                                                                                                                         ATTN: Library
ATTN: NPADE-R
                                                                                                                                                               US Army Engineer Division
                                                                                                                                                                    Europe
ATTN: Technical Library
         Airports and Const. Services Dir.
Technical Information Reference
Centre
KAOL, Transport Canada Building
Place de Ville, Ottawa, Ontario
Canada, KIAONB
                                                                                                                                                                    ATTN: Technical Library
New England
ATTN: Library
ATTN: Chief, NEDED-T
North Atlantic
ATTN: Chief, NADEN-T
South Atlantic
ATTN: Library
Huntsville
ATTN: Library (2)
ATTN: Chief, HNDED-CS
ATTN: Chief, HNDED-CS
ATTN: Chief, HNDED-SR
Lower Mississippi Valley
ATTN: Library
ATTN: Library
ATTN: Library
ATTN: Chief, Engr Div
North Central
     Ft Belvoir, VA 22060
ATTN: Kingman Bldg, Library
     Ft Monroe, VA 23651
ATTN: ATEN
     Ft McPherson, GA 30330
ATTN: AFEN-FED
     USA-WES
ATTN: Concrete Laboratory
ATTN: Library
                                                                                                                                                                    ATTN: Chief, Engr Div
North Central
ATTN: Library
Hissouri River
ATTN: Library (2)
Southwestern
ATTN: Library
ATTN: Chief, SWDED-TM
Pacific Ocean
ATTN: Chief, Engr Div
North Pacific
ATTN: Chief, Engr Div
     6th USA
ATTN: AFKC-LG-E
     US Army Science & Technology Center
- Far East Office
      US Army Engineer District
Buffalo
ATIN: Library
           ATTN: Library
Pittsburgh
ATTN: Library
Philadelphia
ATTN: Library
ATTN: Chief, NAPEN-D
                                                                                                                                                                 Facilities Engineers
Ft Campbell, KY 42223
USAECOM
Ft Monmouth, NY 07703
DFAE, USAIC
FI Benning, GA 31905
TRADOC
Ft Knox, KY 40121
             Baltimore
ATTN: Chief, Engr Div
Norfolk
ATTN: Chief, NAOEN-D
                                                                                                                                                                       TRADOC

ft knox. KY 40121

ft 5111, OK 73503

ft 811ss, TX 79916

HQ, 1st Inf Div & Ft R1ley

HQ, 5th Inf Div & ft Polk

HQ, 7th Inf Div & ft Ord
             Wilmington
                                    Chief, SAWEN-D
            ATTN: Chief, SAMEN-D
Charleston
ATTN: Chief, Engr Div
Savennah
ATTN: Library
ATTN: Chief, SASAS-L
Jacksonville
ATTN: Library
ATTN: Const. Div
Mobile
                                                                                                                                                                  AF Civil Engr Center/XRL
Tyndall AFB, FL 32401
                                                                                                                                                                  Naval Air Systems Command
ATTN: Library
WASH DC 20360
            ATIN: Const. Div
Mobile
ATIN: Chief, SAMEN-C
ATIN: Chief, SAMEN-D
Nashville
ATIN: Library
Memphis
ATIN: Chief, LMMED-DM
Vicksburg
ATIN: Chief, Engr Div
Louisville
ATIN: Chief, Engr Div
St Paul
ATIN: Chief, Engr Div
St Paul
                                                                                                                                                                   Naval Facilities Engr Command
ATTN: Code 04
Alexandria, VA 22332
                                                                                                                                                                    Port Hueneme, CA 93043
ATTN: Library (Code LOBA)
                                                                                                                                                                   Washington, DC
ATTM: Transportation Research Board
ATTN: Library of Congress (2)
ATTN: Dept of Transporation Library
               St Louis
ATTN: Library
               ATTN: Library
Kansas City
ATTN: Library (2)
                                                                                                                                                                    Defense Documentation Center (12)
                                                                                                                                                                    Engineering Societies Library
New York, NY 10017
               Omaha
ATTN: Chief, Engr Div
```

ì

International Lead-Zinc Research Organization, Inc. (5) 292 Madison Ave New York, NY 10017

Concrete Reinforcing Steel Institute (3) 228 North La Saile St Chicago, IL 60601

American Hot Dip Galvanizers Assn, Inc. (5) 1000 Vermont Ave WASH DC 20005

American Concrete Institute (3) P.O. Box 19150, Redford Station Detroit, MI 48219

University of California College of Engineering ATTN: Library Berkeley, CA 94720

American Society for Testing and Materials (2) 1916 Race St Philadelphia, PA 19103

U.S. Steel Corporation ATTN: Mr. Seymour K. Coburn 600 Grant St Pittsburgh, PA 15230